

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Marquette

	Located In	Corner Code ##
1. Public Land Survey	T 45N R 29W	F8
	T R	
	T R	
	T R	
2. Property Controlling in Section	S 21 T R	12
	S T R	9
3. Miscellaneous Property in Sec	S T R	5
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat  
5. Private Claims

I, Keith Sackett, in a field survey on July 28, 19 88, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A Description of original monument and accessories and/or subsequent restoration:

F8	12	9	5
Not set on original survey nor subsequently, apparently.	Not set on original survey nor subsequently, apparently.	Not set on original survey nor subsequently, apparently.	Not set on original survey nor subsequently, apparently.

B Description of corner evidence found and/or method applied in restoring or reestablishing corner.

F8	12	9	5
Established during section subdivision.	Established during section subdivision.	Established during section subdivision.	Established during section subdivision.

C Description of monument for corner and accessories established to perpetuate locating the position of the corner.

F8	12	9	5
Set 1x36" I.P. with 4" aluminum cap.	Set 1" I.D. by 32" I.P. with 4" aluminum cap.	Set 1" by 32 I.P. with 4" aluminum cap.	Set 1 x 30" I.P. with 4" aluminum cap.
12" spruce N57W 4.3', 1/4s BT	18" r. pine S66W 24.9', 1/16s BT	11" w. pine N04W 26.3', 1/16 s	6" cedar N62E 2.6'
7" w. pine S25E 23.3', 1/4s BT	4" spruce N75W 11.5', 1/16s BT	8" w. pine N78W 17.8',	8" cedar S08E 28.6'
8" spruce N60E 14.4', 1/4s BT	8" spruce N59E 6.4', 1/16s BT	8" cedar S50E 47.3'	6" cedar N10W 5.7'

Signed by Keith Sackett Date 10-3-88

Surveyor's Michigan License No 19006

