

OK
B. 11-2-87

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Marquette

(County)

Located In:

Corner Code \neq

1. Public Land Survey

T R

T R

T R

T R

2. Property Controlling
in Section

S 6 T 46N R 23W

1, 2, 3.

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, David Babbitt, in a field survey on 2/3, 19 87,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. West 1/16 corner on the north section line of Section 6. No previous record.
2. East 1/16 corner on the north section line of Section 6. No previous record.
3. North 1/16 corner on the west section line of Section 6. No previous record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1. Set by single proportion to the GLO record between the N $\frac{1}{4}$ corner and the NW
section corner of Section 6.
2. Set MPOL between the N $\frac{1}{4}$ corner and the NE section corner of Section 6.
3. Found re-rod and plastic RLS cap marker GFA 17618 in the single proportion position
between the W $\frac{1}{4}$ corner and the NW section corner of Section 6. Witnessed re-rod
as found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | | |
|--------------------------|------------------------|---|
| 1. DNR Monument | 2. DNR Monument | 3. Re-rod & plastic cap #17618, Marked GFA. |
| 7" w.spruce, S45E, 24.4' | 6" cedar, S77E, 15.9' | 4" bl.spruce, N88W, 15.4' |
| 8" w.spruce, S40W, 28.1' | 6" cedar, N9W, 33.4' | 6" maple, N13W, 15.45' |
| 5" w.spruce, N58W, 12.8' | 6" cherry, N57W, 4.8' | 5" maple, N68E, 22.45' |
| 3" w.spruce, N40E, 3.9' | 6" spruce, S62W, 11.5' | 5" balsam, S24E, 5.0' |

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2				
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by _____, Date _____

Surveyor's Michigan License No. RLS 21558