

# SURVEY & REMONUMENTATION

APR 28 1995

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY  
MICHIGAN  
RECEIVED FOR RECORD  
1994 DEC 29 PM 1:56

For corners in **COMMISSION**

Marquette

(County)

Located In:

Corner Code #

1. Public Land Survey

T. 46N R. 25W

M-11

T. 46N R. 24W

A-11

T. R.

T. R.

2. Property Controlling  
in Section

S. T. R.

S. T. R.

3. Miscellaneous

S. T. R.

Property in Sec.

S. T. R.

4. Lot No. , Recorded Plat

5. Private Claims

RATIFIED BY PEER GROUP  
P.A. 345 OF 1990

DATE Sept 26, 1994

LIBER

1 PAGE 233

Register of Deeds Stamp & File Number

Michael Mileski

September 94

I, Michael Mileski, in a field survey on September 94, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-11; Northeast Corner Section 36;

See back of form.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-11; Northeast Corner Section 36;

Found a 1" iron pipe projecting 10" above ground in agreement with the northeast M.C.R.C. new bearing tree which is presently alive (16" dia.) having partially healed mid-trunk blaze with scribing evident.

State Plane Coordinates:

Grid System - NAD 83

Zone Number - 2111 Michigan North

Units - International Feet

Y = 570548.69604

X = 26154330.07337

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-11; Northeast Corner Section 36;

Replaced found 1" iron pipe with 2" I.D. x 30" aluminum pipe with 3" aluminum cap (Berntsen A1NB30) appropriately stamped as to location.

Set 60d spike	NW/side	6" Jack Pine	N46°E	75.42'
Set 60d spike	SW/side	4" Red Maple	S34°E	42.90'
Set 60d spike	SW/side	11" Red Oak	N50°W	83.35'
Set 60d spike	W/side	8" Red Oak	N02°W	74.97'
		Location Post	North	1.5'

All of the above new bearing trees marked with upper and lower face blazes and scribed "NBT".

Signed by

Michael Mileski

Date 21 Nov 1994

Surveyor's Michigan License No.

39091