

1993

COMMISSION

JOB NUMBER: 93300

SHEET NO. : 1-420

For corners in

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE
(County)

Located In:

Corner Code #

- | | | |
|------------------------------------|---------------------------|------------|
| 1. Public Land Survey | T <u>46N</u> R <u>24W</u> | <u>D-1</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, GERALD W. CARLSON, in a field survey on Saturday, December 11, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

D-1: North Quarter Corner Section 5. Not part of original survey.

1980 - G. Carlson set a 5/8" iron with RLS cap proportionately proportionately on line between the NE and NW corners of Section 5, 5 ft. South of an old East/West fence line referenced by:

6" Cedar	East	12.29 ft.
12" Cedar	S09E	6.33 ft.
8" Cedar	S73W	2.74 ft.
7" Yellow Birch	N31E	5.92 ft.

26.40 ft. West of the South 1/4 Corner of Section 32, T47N-R24W.
L4 RC, Pg. 23

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993 - Found 5/8" iron with RLS cap 24589 as described in G. Carlson witness in 1980 replaced with Marquette County Survey Monument. Peer group ratification 12-6-93.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993 - Replaced existing marker with a 2 1/8" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:

7" Yellow Birch	N32E	5.96 ft.	Carlson BT
6" Cedar	Due East	12.54 ft.	Carlson BT
12" Cedar	S12E	6.43 ft.	Carlson BT
8" Cedar	S70W	2.49 ft.	Carlson BT
6" Cedar	N68W	19.06 ft.	

Bk. 2, Pg. 120

Signed by Gerald W. Carlson

Date 12-28-93

Surveyor's Michigan License No. 24589

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD
1993 DEC 29 AM 10:36
Gerald W. Carlson
REGISTERED SURVEYOR
No. 24589
LIBER 1 PAGE 33
Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2				
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

