

1999 DEC 22 AM 11: 25

Patricia A. Manley
REGISTER OF DEEDSLAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in
MARQUETTE
(County)

Located In:

Corner Code #

1. Public Land Survey		T <u>46N</u> R <u>25W</u>	<u>C-1</u>
		T <u> </u> R <u> </u>	<u> </u>
		T <u> </u> R <u> </u>	<u> </u>
		T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>
	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>
	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>

4. Lot No. , Recorded Plat
5. Private Claims

I, GERALD W. CARLSON, in a field survey on November 4th, 19 99, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-1: Corner common to Sections 5 and 6, T46N-R25W on the North Township line.
1845: William Ives original subdivision survey notes describe the corner monument as a wood post 36 links West of corner of Sections 31 and 32, T47N-R25W referenced by:
8" Spruce Pine S35W, 31L 7" Spruce Pine S06E, 06L

1990: A survey calculation sheet by Gerry Carlson, P.S. #24589, indicates the corner distance S01-59-08E, 5243.48' to the section corner common to Sections 5, 6, 7, and 8, T46N-R25W.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-1: 1999: No original corner evidence found. Corner position was established 23.76' West of the Southeast corner of Section 31, T47N-R25W and on line between the Southeast corner and the South quarter corner of Section 31, T47N-R25W. Distance West is 2636.29', East is 2635.64'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-1: 1999: Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Monument is flush with the ground. Referenced by:

7" Jack Pine	S06E,	30.53'	9" Jack Pine	S23W,	27.43'
11" Jack Pine	S83W,	33.17'	13" Jack Pine	N29W,	23.55'
S.E. Cor. Section 31 (sc)	S90E,	23.76'			

Green Steel Sign Post w/ Yellow Survey Marker Sign S08W, 3.05'

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

RATIFIED BY PEER GROUP

P.A. 345 OF 1990

Garry J. Bussard
DATE 11/1/99Signed by Gerald W. CarlsonDate 12-8-99Surveyor's Michigan License No. 24589

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1976

REVISED JAN., 1983

REVISED OCT., 1995