STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

LAND CORNER RECORD

	Marq	uette COUNTY
	T <u>46 n</u>	R26 W
DESCRIPTION OF CORNER	E $1/16$ corner for sections $\frac{28}{33}$	
CORNER MONUMENT	1" pipe with 4" aluminum cap	
DATE MONUMENT PLACED AND WITNESSED		
WITNESSES TO CORNER 4" W. Pine (E 1/16) (BT) N 3° E, 14.0'		
N 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	ц" В. Spruce (E 1/16) (ВТ) S 85° E, 2	29.61
	AND	
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Mid-point on line between section corner east and 1/2 west. No evidence of lines or occupation.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

REGISTERED LAND SURVEYOR

DATE ____11/23/70_

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68