

1994 DEC 28 PM 5:56

JOB NUMBER: 94030

SHEET NO. : 1-489

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MARQUETTE  
(County)

Located In:

Corner Code #

Patricia A. Monley  
REGISTER OF DEEDS

1. Public Land Survey T 47N R 27W D/E-13  
T 46N R 27W D/E-1 ✓  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

LIBER 1 PAGE 160  
Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, GERALD W. CARLSON, in a field survey on Tuesday, December 20, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

## A. Description of original monument and accessories and/or subsequent restoration:

D/E-13: Meander Corner on the West side of Long Lake on the South line of Section 32, T47N-R27W.  
1846: Austin Burt's original survey notes described the corner monument as a post referenced by:  
10" White Pine N27 1/2E 14 1  
1965: A survey of Section 33, T47N-R27W by Cleveland Cliffs Iron Company R.J. Brotherton in 1965 indicates he set the meander corner from a pine stump BT 714.15' West from the calculated section corner in Long Lake. No corner accessories given.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found and accepted a 3/4" iron pipe as M.C. referenced in Part "A" above. Distance West is 2091.36' to D-13 and distance East is 3384.89' to F-13.

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11			
5												
6	18		17		16		15		14			
7												
8	19		20		21		22		23			
9												
10	30		29		28		27		26			
11												
12	31		32		33		34		35			
13												

RATIFIED BY PEER GROUP  
P.A. 345 OF 1990Larry J. Bussan  
DATE Nov 21, 1994

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Replaced 3/4" diameter iron pipe with a 2 1/2" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:

3" Spruce N69E 27.51 ft.

4" White Pine S52E 9.65 ft.

7" Cedar S18W 11.40 ft.

7" Spruce S80W 37.28 ft.

Steel sign post N09W 1.60 ft.

Monument is located 18' North of the waters edge and 38' West of the waters edge.

Bk. 5, Pg. 127

Signed by Gerald W. CarlsonDate 12-22-94Surveyor's Michigan License No. 24589