

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

(MARQUETTE COUNTY)

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY.....	T. 46 N. R. 29 W. <input checked="" type="checkbox"/>	#L-5
2. PROPERTY CONTROLLING IN SECTION 13	T. 46 N. R. 29 W. <input checked="" type="checkbox"/>	#1
3. MISCELLANEOUS PROPERTY IN SECTION.....	T. N. R. E. W. <input type="checkbox"/>	
4. LOT NO., RECORDED PLAT.....		
5. PRIVATE CLAIMS.....		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October 15, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on, 19....., found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner L-5 (1/4 corner between Sections 12 & 13, T46N, R29W):

Tamarack post (Not found. No subsequent monuments found.)
Tamarack 14 East 1-1/2 (Not found. No subsequent accessories found.)
Tamarack 6 S74W 27 (Not found. No subsequent accessories found.)

Corner 1 (West 1/16 corner between Sections 12 & 13, T46N, R29W):

Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner L-5: Restored on line between Sec. Cor. 40.2385 ch. E and
Sec. Cor. 40.2385 ch. W.

Corner 1: Established on line between Sec. Cor. 20.119 ch. W and
1/4 cor. 20.119 ch. E.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner L-5: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
Tamarack 7 N72°W (mag.) 20.4 ft. "1/4S, NBT"
Tamarack 4 N17°E (mag.) 13.9 ft. "1/4S, NBT"
Declination 1° 50' West.

Corner 1: ⊕ chiselled in a crumbly granite boulder at ground surface, with a
5" x 5" x 5' squared & scribed cedar post set N33°E (mag.) 1.5 ft.
for a guard post.

Black Spruce 7 N63°E (mag.) 19.1 ft. "1/16S, BT" Witnesses are to the ⊕.
White Birch 11 N64°W (mag.) 25.8 ft. "1/16S, BT" Declination 2° 45' West.

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE March 7, 1980

MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

