

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: 09-Jun-16

For corner(s) in: Marquette County

Original Public Land Survey Corner

Corner Code

S T 46N R 29W
S T R
S T R
S T R

I6

Property Corner

1/16 Corner Code

S T 46N R 29W
S T R
S T R
S T R

J6

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15	●	14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A. Corner History

(I6) Quarter corner common to Sections 14 and 15. Original corner was deemed lost and the position was reestablished in 1979 by A.O.Enger RLS on line between Section corners I5 40.158 chains north and I7 40.641 chains south. Set 1"IDx36" I.pipe with 3 3/4" aluminum cap. B.Spruce 12" N47°E 6.5', B.Spruce 11" N59°W 11.8'.

(J6) Center of Section 14. 1982 - Established by K.L.Sackett RLS at the intersection of 1/4 lines. Set 1"IDx32" I.pipe with 4" aluminum cap. 6" Spruce S37°E 6.5', 16" W.Pine N19°E 10.1', 4" Spruce N13°W 4.1'.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

(I6) Found the 1979 monument in good condition, as described, and at record bearing and distance from the 1979 NBTs. The B.Spruce NE is a rotting stump. The B.Spruce NW is dead and down with scribing visible. No measurements were made at this time to verify the accuracy of the 1979 position. This corner is being recorded to update the accessories.

(J6) Found the 1982 monument in good condition and at record bearing and distance from the remains of two of the 1982 witnesses: The W.Pine NE is a 20' high dead stub with scribing visible, the Spruce NW is a rotted mass, no markings visible. Other than a measurement to I6, which was found to be 2642.34' (R=2642.53' K.L.Sackett 1982), no measurements were made at this time to verify the accuracy of the 1979 position. This corner is being recorded to update the accessories.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

(I6) Fd. 1"ID I.pipe with 3 3/4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" Balsam S73°E 5.25' mrkd "1/4S NBT"
4" Balsam S46°W 3.35' do
8" R.Pine N78°W 18.2' do
7" twin B.Spruce N30°W 27.95' do
Found sq'd post adjacent.
E= 7930150.023 N= 178363.565

(J6) Fd. 1"ID I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" Spruce S80°E 7.45' mrkd "C1/4 BT"
4" R.Pine S31°E 6.6' do
4" R.Pine S40°W 10.95' do
5" R.Pine N31°W 8.75' do
Set sq'd cedar post adjacent.
E= 7930955.179 N= 178351.047

Bearings are magnetic. Coordinates are MCS83, NAD83(2011) Epoch 2010.00, in meters.
Coordinate Reference: NGS PID AA8080, E= 7925456.741 m. N= 192972.689 m.

Stephan J. Szyszkoski

06/13/2016

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

