

SURVEY &  
REMONUMENTATION

JOB NUMBER: 94030  
SHEET NO. : 1-444

APR 28 1995

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY  
MICHIGAN  
RECEIVED FOR RECORD

1994 DEC 29 AM 10:55

For corners in

MARQUETTE  
(County)

COMMISSION

Located In:

Corner Code ##

- |                                       |       |       |     |
|---------------------------------------|-------|-------|-----|
| 1. Public Land Survey                 | T 47N | R 25W | I-1 |
|                                       | T     | R     |     |
|                                       | T     | R     |     |
|                                       | T     | R     |     |
| 2. Property Controlling<br>in Section | S     | T     | R   |
|                                       | S     | T     | R   |
| 3. Miscellaneous<br>Property in Sec.  | S     | T     | R   |
|                                       | S     | T     | R   |

Patricia A. Stanley  
REGISTER OF DEEDS

LIBER

1 PAGE 117

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, GERALD W. CARLSON, in a field survey on Wednesday, December 28, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

I-1: Section Corner common to Sections 2 and 3, T47N-R25W.

1845: A.D. Sullivan's original survey notes describe the corner monument as being set 12 1 East of Section Corner common to Sections 34 and 35, T48N-R25W. No description of corner monument given. Referenced by:

8" Cedar S61E, 13 1

6" Cedar S11W, 15 1

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Corner established 7.92' (12 L) East of the found Corner to Sections 34 and 35 on line with the SW and S 1/4 Corners of Section 35. The distance West is 2633.02' and the distance East is 2623.27'.

RATIFIED BY PEER GROUP  
P.A. 345 OF 1990

Larry J. Busome  
DATE Oct. 3, 1994

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Set a 2 1/2" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:

12" Maple S49W 20.35 ft. Jamros NBT

8" Maple N45W 17.74 ft. Jamros NBT

8" Maple N71E 37.37 ft. Jamros NBT

10" Maple S13E 15.07 ft. Jamros NBT

Steel sign post East 0.95 ft.

Monument is 0.25' above ground and located on Northwesterly slope of steep ridge.

Bk. 8, Pg. 89



Signed by Gerald W. Carlson

Date 12-29-94

Surveyor's Michigan License No. 24589