

JOB NUMBER: 93300  
SHEET NO. : 1-351  
For corners in

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

	Located In:	Corner Code ##
1. Public Land Survey	T 47N R 24W	A-6
	T 47N R 25W	M-6
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	

LIBER 1 PAGE 45  
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat  
5. Private Claims

I, GERALD W. CARLSON, in a field survey on Tuesday, December 14, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-6: Quarter Corner common to Section 18, T47N-R24W and Section 13, T47N-R25W. 1844: William A. Burt's original survey notes describe the corner monument as a wood post referenced by:

12" Sugar N68W, 13 1  
20" Hemlock S60E, 22 1

1960 - Gregory Shadko found an old iron (C.M. Cade, 1936) placed 4" x 36" iron pipe filled with concrete and capped with brass plate 12" below surface referenced by:  
NW corner of house basement S44 degrees 30 min.  
East 154.0 ft.  
9" White Pine S22W 88.5  
6" White Pine S55 degrees 30 min. West 76.7 ft.  
14" Transmission Pole N39W 37.82 ft. (See reverse side)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993 - Found DNR monument in water box in the centerline of Ford Road extended just West of Townline Road 1.6 ft. below grade. This monument is the one set by Shadko in 1960. Distances East and South check 0.04' E. and 1.83'S. according to Shadko's survey. Left DNR monument as found. Peer group ratification 12-6-93.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993 - Found Michigan Conservation Department brass cap in water box 1.0 ft. below grade referenced by nails in:

6" White Pine S55W 33.65 ft.  
6" White Pine S87W 73.38 ft.  
11" White Pine N50E 52.06 ft.  
Bk. 2, Pg. 154



Signed by Gerald W. Carlson Date 12-28-93

Surveyor's Michigan License No. 24589

Record No. 351

Part "A" Continued:

- 1973 - Robert Cambensy indicates monument with brass cap in the recorded plat of Woodvale No. 1.
- 1974 - Same statement Woodvale No. 3
- 1977 - Same statement Woodvale No. 4
- 1978 - Robert F. Cambensy indicates the same monument recorded plat of Glen Meadows.

6/11/78  
#900  
H. J. Campbell