

SURVEY &
REMONUMENTATION

APR 28 1995

JOB NUMBER: 94030

SHEET NO. : 1-516

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

1994 DEC 28 PM 5:58

For corners in

Patricia A. Mankoff
REGISTER OF DEEDS

MARQUETTE
(County)

Located In:

Corner Code ##

- | | | | |
|------------------------------------|-------|-------|----|
| 1. Public Land Survey | T 47N | R 26W | D1 |
| | T | R | |
| | T | R | |
| | T | R | |
| 2. Property Controlling in Section | S | T | R |
| | S | T | R |
| 3. Miscellaneous Property in Sec. | S | T | R |
| | S | T | R |

LIBER 1 PAGE 182
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, GERALD W. CARLSON, in a field survey on Wednesday, December 21, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

D1: North 1/4 Corner of Section 5, T47N-R26W. Referenced by:
Not part of original survey. No date given: Maas 6" Poplar, S20E, 59.44'
Triangulation Coordinates obtained from CCI indicate 4" Poplar, S71W, 51.98'
the North 1/4 Corner of Section 5 as S70.40, 2635.17E. 6" Poplar, N31W, 65.95'
1978: Certificate of Survey, by Joseph Wasie, RLS #15415, recorded in Liber 328, Page 692, indicates the North 1/4 Corner of Section 5 as a found 1" iron pin.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Did not accept the 1" iron pin referenced above in part "A". This 1" iron pin should be the South 1/4 Corner of Section 32, T48N-R26W. The distances East and West fit more reasonably, due to double corners along this line. Corner position established equidistant between the Northwest and Northeast Corners of Section 5 and on line between the South 1/4 and Southeast Corners of Section 32, T48N-R26W. Distances West and East are 2620.87'. The South 1/4 Corner of Section 32, T48N-R26W is West, 51.03'.

RATIFIED BY PEER GROUP
P.A. 345 OF 1990

Larry J. Bussard
DATE Dec 6, 1994

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Set a 8.7' long, 3/4" diameter re-rod capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:
10" Poplar S34E 92.08 ft.
8" Poplar S20W 64.64 ft.
4" Poplar N65W 39.47 ft.
5" Poplar North 60.65 ft.
Face of 6" diameter, 5.4' high metal test well casing S53E 53.78 ft. "Hakala Well & Pump Negaunee, MI"
Steel sign post N15W 1.61 ft.
Monument is 0.5' above ground and located in swampy area of Poplar and small brush. Bk. 6, Pg. 149

igned by Gerald W. Carlson

Date 12-28-94

urveyor's Michigan License No. 24589

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 20, 1971
REVISED MAY 22, 1975
REVISED JAN., 1983

