

JOB NUMBER: 93300

SHEET NO. : 1-407

For corners in

MARQUETTE
(County)

Located In:

Corner Code #

1. Public Land Survey

T 47N R 27W

T 47N R 28W

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, GERALD W. CARLSON, in a field survey on Tuesday, December 21, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-12: Quarter Corner common to Section 31, T47N-R27W and Section 36, T47N-R28W. 1846: Austin Burt's original survey notes describe the corner monument as a Cedar post referenced by:
6" Spruce S50W, 5 l.
(No Species) N35E, 9 l.
No date given- Marquette County Road Commission field book #512 indicates a post at a fence intersection.
No corner accessories given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993 - Set spike in center of old rotted and broken off fence corner post and strands of barbed wire to North and West. The point to this fence post is in good condition. Replaced the corner fence post with a Marquette County Survey Monument. Peer group ratification 12-20-93.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993 - Set a 2 1/8" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:
4" Black Spruce N66W 29.39 ft.
10" White Birch N36E 24.53 ft.
6" Black Spruce N84E 35.15 ft.
6" Black Spruce S47W 20.12 ft.
Monument is flush with ground in swampy Spruce woods.
Bk. 5, Pg. 4

Signed by Gerald W. Carlson

Date 12-28-93

Surveyor's Michigan License No. 24589

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

LIBER 1 PAGE 72
Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

