

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

For corners in
MARQUETTE
(County)

Located In:

Corner Code #

1996 DEC 20 PM 2:12

Patricia A. Monroy
REGISTER OF DEEDS

1. Public Land Survey		<u>T 48N R 26W</u>	<u>E-12</u>
		T <u> </u> R <u> </u>	<u> </u>
		T <u> </u> R <u> </u>	<u> </u>
		T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>
in Section	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>
Property in Sec.	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>

LIBER

1 PAGE 351

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, GERALD W. CARLSON, in a field survey on OCTOBER 24TH, 19 96, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
E-12: Quarter Corner common to Sections 32 and 33.

1845: Sam U. Hill's original subdivision survey notes describe the corner monument as a wood post referenced by:

8" Fir S41E, 10 L 14" Cedar N43W, 19 L

No Date: A Field Map of Section 33 by R.A. Brotherton for C.C.I. Co. indicates the corner as a T Rail. Distance East, 2834' to the Center 1/4 Corner Section 33. No accessories given.

No Date: A sketch of Section 33 by R.A. Brotherton for C.C.I. Co. indicates the corner. Distance East, 2834' to the Center 1/4 Corner, and Distance East, 5464' to the East 1/4 Corner Section 33. Distance between a Stake at the N.W. Corner Section 33, and an Iron Pipe at the S.W. Corner Section 33 is shown as 5354.5'. No accessories given.

No Date: A Field Map of Section 32 by R.A. Brotherton for C.C.I. Co. indicates the corner as an Iron. No accessories given.

1986: An LCRC recorded in 1987 by Larry J. Bussone P.S. #25833, in L. 5, RC Pg. 107, indicates no original evidence found. He found an Iron Rail 1 1/2' below ground, and indicates the corner has been in the Cleveland Cliffs Iron Co. records since the early 1900's - origin unknown. Referenced by:

8" Poplar S48W, 08.8' 6" Sq. Post S60W, 20.5'
P. Pole N54W, 93.2' P. Pole N43.5E, 65.0'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-12: 1996: No original evidence found. Found and accepted a Railroad Rail, 1.5' below ground. Checked Line Call: South, 1.00 Chain (66'), Leave Cedar Swamp. Measured Call: South, 37' to edge of lowland. Distance and Bearing to found reference check reasonably well with those recorded in 1987 by Larry Bussone. Distance North is 2577.25' and Distance South is 2668.40'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-12: 1996: Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument over the top of found railroad rail. Monument was cut off and flanged, made to sit flush with the ground, and stamped to identify the corner. Checked existing reference: 6" Square R/W Post S64W, 21.12' to C/L (Bussone Accessory)

Established references:

3" Cherry N15E, 15.68' 9" Balsam S01E, 55.03'
5" Tw. W. Birch S61W, 48.06' 6" W. Birch S81W, 39.89'
Green Steel Sign Post w/ Yellow Survey Marker Sign S15W, 2.0'

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed. Bk. 9, Pg. 99.

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

RATIFIED BY PEER GROUP
P.A. 345 OF 1990

Larry J. Bussone
DATE 12/14/96



signed by Gerald W. Carlson Date 12-19-96

Surveyor's Michigan License No. 24589

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995