SURVEY & REMONUMENTATION

MAY 2 2 1997

MARQUETTE

For corners in

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code #

Located In:

MARQUETTE	COUNTY				
MICHIGAN					
NEOFINED FOR	3 mm # 25/51				

RECEIVED FOR RECORD

1996 DEC 20 PM 2: 14

Patricia	A.	1	Jones	lac	ردې
Patricia REGISTER	OF.	lii.	EOS	Ø	Sui

(County)					it! Ii	15 (7,8)	ÇI' de	11115 V	$\mathcal{O}_{\ell_{\ell}}$
1. Public Land Survey	T_48N R_26W_ TR TR	<u>L-11</u>							V
2. Property Controlling S	TR			Registe	LIBE or of Deeds			PAGE 3	71
4. Lot No, Recorde	d Plat								
5. Private Claims				АВ	C D E	F G	H I	ј к	LM
				2 - 6 -			3-	_2 ~	1_
I, GERALD W. CARLSON do hereby state that under requirementioned in lines 1 and 2 above we required in the current manual of surve Bureau of Land Management or by mentioned in lines 3, 4 and 5 above we hand Surveyors or by a Decree of recovered, found as expressed below:	ents of P.A. 74, Michigan P.A. vere in conformance with regular by instructions of the United State a decree of a Court of Law as were in conformance with the rual Court of Law; established, a	of 1970, the ations and rule as Department and/or that the ales of the Mic	e corner points es therefore as of the interior, e corner points higan Board of	3 4 7 7 5 6 18 7 8 19 9	17-	16	-10	-11	-12- -13- -24-
NOTE: Not more than 2 corners,	, all in the same town and ran	ige, may be i	ecorded	10-30-	29-	-28	-27-	-26-	-25
on this certificate.				11	 	+	-}}-		
A. Description of original monum L-11: <u>Quarter Corner common to S</u> 1845: Sam U. Hill's original subdiv wood post referenced by: 4" Alder N47E, 13	Sections 25 and 36, vision survey notes describe the	he corner mo			32 ATIFIED A. 345, O			ROUP	36
No Date (Circa 1900): Charles Cu	ummings, in Record of Survey	ıs Pa. 191. i	ndicates the	 -	Lan	7.41	(Vec	oan.	L
corner being equidistant on line be	tween the Southwest and So	utheast corn	ers at a distance	of 2673	ATE	12-11	<u>6/79</u>		
No Date: Circa late 1940's to ear the North edge of a creek. 1949: A field sketch by R.A. Broth							p 24 f	eet No	orth of
1990: A Survey Sketch by R.L. Ja Distance is shown as 2666.2' com									9.16'.
B. Description of corner evidence L-11: 1996: Searched and found i Northwest and Northeast Corners of a Stream." Distance East is 266	no original or subsequent corr of Section 36. The position cl	ner evidence. hecked well	This corner was	s set equid					
C. Description of monument for out- 1-11: 1996: Set a 3/4" diameter be stamped to identify the corner. Mo Referenced by:	by 6' long Iron capped with a	3 1/4" diam	eter aluminum ta	blet Marq	uette Cou	inty Su			ent
7" Balsam S30E, 116.11' 9" R. Pine N19W, 257.88' Green Steel Sign Post w/ Yellow S	7" Balsam 8" R. Pine urvey Marker Sign	S03W, N21W, S18E,	112.48' 290.32' 3.0'						
Note: Bearing trees have painted fa 3k. 10, Pg. 115; Bk. 9, Pg. 109.				amped B.1	r. Tags at	ffixed.			

SURVEYOR No. 24589 urveyor's Michigan License No.____ ROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT.. 1996

TE OF BICH

GERALD W. CARLSON