

FEB 21 2001

## SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MARQUETTE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 48N R 26W

E-1

T R

T R

T R

T R

2. Property Controlling  
in Section

S

T R

S

T R

3. Miscellaneous

S

T R

Property in Sec.

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, GERALD W. CARLSON, in a field survey on November 9 TH, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

## A. Description of original monument and accessories and/or subsequent restoration:

E-1: Corner common to Sections 4 & 5.

1845: Sam U. Hill's original subdivision survey notes describe the corner monument as a wood post being 10 links East of the corner common to Sections 32 & 33, T49N-R26W, referenced by:

14" Sugar S59E, 42 links 18" Sugar S46W, 69 links

No subsequent records recovered

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

RATIFIED BY PEER GROUP  
P.A. 345 OF 1990Larry J. Bussan  
DATE 11/6/00

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-1: 2000: SCA survey crews conducted a thorough search of the area and found no evidence of monumentation excepting a nearby tree with a blue paint line from the South and a corner locator tag affixed. The GLO line call of 152.5' South "Knob of rock to right of line." was measured by SCA to be 219.6' South. Corner position was established at the GLO offset distance and on line between the SW and S 1/4 corners of Section 33, T49N-R26W.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-1: 2000: Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Monument is 0.2' above ground. Referenced by:

8" Maple	N02E, 13.91'	8" Maple	N53E, 10.94'
9" Maple	S44E, 11.60'	20" Oak	S52W, 48.41'

SW Corner Section 33, T49N-R26W S89°53'40"W, 6.60'

Green Steel Sign Post w/ Yellow Survey Marker Sign S03W, 3.04'

Distance East 2642.66', distance West 2648.54'.

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.

Bk. 15, Pg. 71 T48N-R26W Corner Search Sheet 2000035



Signed by

Gerald W. Carlson

Date

12-19-00

Surveyor's Michigan License No.

24589FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995