

SURVEY &  
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MARQUETTE

(County)

Located in:

Corner Code #

1. Public Land Survey

T 48N R 26W

H-1

T      R     

T      R     

T      R     

2. Property Controlling  
in Section

S      T      R     

S      T      R     

3. Miscellaneous  
Property in Sec.

S      T      R     

S      T      R     

4. Lot No.         , Recorded Plat         

5. Private Claims                                 

I, GERALD W. CARLSON, in a field survey on November 14 TH, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

**A. Description of original monument and accessories and/or subsequent restoration:**

**H-1:** North Quarter Corner of Section 3, T48N-R26W.

Corner not established during Original GLO Survey.

No subsequent records recovered

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

**H-1: 2000:** SCA survey crews conducted a thorough search of the area and found no evidence of monumentation. Corner position was established equidistant between the NW and NE corners of Section 3 and on line between the SE and S 1/4 corners of Section 34, T49N-R26W.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

**H-1: 2000:** Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Monument is flush with ground and rocks have been placed in hole because of subsurface water and muck. Referenced by:

6" Cedar N16E, 11.30'

13" Cedar

N69E, 30.91'

7" Maple S14W, 70.48'

8" Y. Birch

N78W, 10.38'

South 1/4 Corner Section 34, T49N-R26W S89°52'46"W, 14.48'

Green Steel Sign Post w/ Yellow Survey Marker Sign S14E, 5.30'

Distance East 2637.71', distance West 2637.71'.

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.

Bk. 15, Pg. 83 T48N-R26W Corner Search Sheet 2000035

Signed by Gerald W. Carlson

Date 12-19-00

Surveyor's Michigan License No. 24589

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1995

MARQUETTE COUNTY  
MICHIGAN  
RECEIVED FOR RECORD

2000 DEC 22 AM 10:18

*Patricia D. Monley*  
REGISTER OF DEEDS

LIBER **R2** PAGE **289**  
Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		6		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

RATIFIED BY PETER GROH

P.A. 345 OF 1990

*Larry J. Bussone*  
DATE 11/6/00

