

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

2000 DEC 22 AM 10:17

For corners in
MARQUETTE
(County)

Located In:

Corner Code #

Patricia R. Manley
REGISTER OF DEEDS

1. Public Land Survey T 49N R 26W E-13
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

LIBER **R2** PAGE 275

Register of Deeds Stamp & File Number

I, GERALD W. CARLSON, in a field survey on November 9 th , 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
E-13: Corner common to Sections 32 & 33, T49N-R26W.

1844: Austin Burt's original Township Line survey notes of T49N-R26W, describe the corner monument as a 18" Hemlock.

No subsequent record evidence recovered.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

RATIFIED BY PEER GROUP
P.A. 345 OF 1990

Larry J. Bussone
DATE 11/6/00

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-13: 2000: No original corner evidence found. SCA survey crews conducted a thorough search of the area and found no evidence of monumentation excepting a nearby tree with a blue paint line from the South and a corner locator tag affixed. The GLO line calls North and South matched reasonably well with the calculated position as did the calls to the East and West. Corner position was established on the latitudinal curve by single proportionate measurement between the Southeast Corner of Section 31, T49N-R26W and the Southeast corner of Section 36, T49N-R26W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-13: 2000: Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Monument is 0.2' above ground. Referenced by:

8" Maple N27E, 15.20' 8" Maple N68E, 16.52'
9" Maple S60E, 16.73' 20" Oak S47W, 43.35'

Northeast Corner of Section 5, T48N-R26W N89°54'09"E, 6.60'
Green Steel Sign Post w/ Yellow Survey Marker Sign N24W, 3.83'
Distance East 2638.37', distance West 2638.37'.

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.

Bk. 15, Pg. 69 T49N-R26W Corner Search Sheet 2000035



Signed by *Gerald W. Carlson*

Date 12-19-00

Surveyor's Michigan License No. 24589

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1976
REVISED JAN., 1983
REVISED OCT., 1995