

JUL 03 2000

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

1996 NOV 22 AM 11:06

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Marquette

(County)

Located In:

Corner Code #

1. Public Land Survey

T 50N R 28W

81

2. Property Controlling
in Section

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

S

T

R

Patricia R. Monley
REGISTER OF DEEDS

LIBER R1 PAGE 309
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

Sep 26 1995

I, Stephan J. Szyszkoski, in a field survey on , 19 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

(81) North Quarter corner, Section 6. Corner not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(81) Found no evidence of prior monumentation at the corner position. Established the corner on the Fifth Correction Line at the proportionate North Latitude between the perpetuated original corner at the South 1/4 corner, Sec. 34 T51N-R28W, and a 1 1/2" pipe found at the standard corner between Sections 32-33 T51N-R28W, and 40 chains, proportionate measure, West of the closing corner between Sections 5-6 T50N-R28W. Record distances used in the proportion for departure were derived from the original record of survey for T50N-R28W by Abner B. Wood, 1852, and Austin Burt, 1845. At the position for the corner, I placed a 1"IDx36" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. From the corner monumented, The Standard corner common to Sections 33-34, T51N-R28W is 81.77' east, along the Correction Line.

RATIFIED BY PEER GROUP
P.A. 345 OF 1990

Larry J. Bussone
DATE 10/28/96

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(81) Set 1" pipe with 4" MDNR cap.

Blazed and scribed the following bearing trees:

8" Sugar S65W 7.4' "1/4S BT"

10" Sugar N70W 9.1' "1/4S BT"

12" Sugar S32E 13.4' "1/4S BT"

12" Sugar N53E 16.4' "1/4S BT"

A 4" Squared Sugar bears S35E 3.1'.

Bearings are magnetic.

MDNR monuments are 1"IDx32" iron pipe capped with a 4" dia. cast aluminum Michigan Department of Natural Resources tablet, stamped with Township, Range, corner ID, date of placement, and "PS 33986".

New bearing trees are marked with a 3H blaze and a lower blaze at the root crown. The blazes are scribed as indicated in quotation marks at left, with NBT or BT (as noted) being on the lower blaze. Distances are horizontal (unless noted) and measured from the corner to the inside of a notch cut into the bottom of the lower blaze.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11-5-96

For the Michigan Department of Natural Resources - Forest Management Division