

1893

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On 12/28, 1993
Chairman

For corners in
MENOMINEE
(County)

Located In:

Corner Code #

1. Public Land Survey T 32N R 27W H-7
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

I, WILLIAM LENCA, in a field survey on October 21 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
ORIGINAL B.T.'s: Tamarack, 14", SOUTH, 07 lks
Tamarack, 11", N14°E, 20 lks

Original Survey by James H. Mullett in 1848. All original evidence for this corner position has been destroyed by county road improvements.

PERPETUATION: William Lenca, RLS No. 26461, in October, 1987 - LCRC No. 779, Book 1

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" dia. Iron Pipe 18" long in the centerline of an East-West County Road and in line with an ancient fence line running North from this location. This position fits with occupation at the W1/16 Line and has been used by local surveyors as the corner position. This corner location is is accepted as the best available evidence of the position of the original corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 24" iron with cap stamped for corner

10" cedar	N40°E	68.96 feet
7" cedar	S25°E	48.20 feet
4" cedar	S44°W	37.02 feet
9" cedar	N30°W	43.71 feet
Metal Survey Sign Post	S03°W	26.00 feet

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape.
All distances to trees are to nails in side of tree.

Signed by William Lenca

Date December 20, 1993

Surveyor's Michigan License No. 26461

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1983

RECEIVED FOR RECORD
93 DEC 29 PM 3:00
PAGE # 10
BARBARA MORRIS
REGISTER OF DEEDS
MENOMINEE, MI 498
Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

