

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On 12/28 19993
Mark Davis
Chairman

For corners in
MENOMINEE
(County)

Located In:

Corner Code #

- Public Land Survey T 32N R 27W I-6
T R
T R
T R
- Property Controlling S T R
in Section S T R
- Miscellaneous S T R
Property in Sec. S T R
- Lot No. Recorded Plat
- Private Claims

Register of Deeds Stamp File Number

I, WILLIAM LENCA, in a field survey on Sept. 13 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
ORIGINAL B.T.'s: No Bearing Trees Shown in Original Field Notes.

Original Survey by James H. Mullett in 1848.

PERPETUATION: George B. Wilson, RLS No. 17607, re-established this corner, recorded in LCRC No. 205, Book 1, in Dec. 1979.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

In the early 1980's, I tied in and used the concrete monument which had been set in the above re-establishment by George B. Wilson. This monument was destroyed in 1984 by the installation of underground telephone lines. We re-set this corner using a 3/4" diameter aluminum rod 5 feet long with a 3-1/4 inch diameter aluminum cap. This corner falls in line with the centerline of a county road running East from this location, an old occupation running West from this location and was established on line between the Section Corners to the North and South. This corner has been used by local surveyors for more than 15 years, and is accepted as the best available evidence of the position of the original corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Found 3/4" dia. Alum. Rod/3-1/4" dia. Alum cap stamped for corner:

Chisled cross in NW Cor. of cement headwall	N40°E	69.05 feet
Set 5/8" x 24" Iron Rod/2" Alum. cap marked WITNESS CORNER	S56°W	22.80 feet
Set 5/8" x 24" Iron Rod/2" Alum. cap marked WITNESS CORNER	N55°W	39.12 feet
3/4" dia. Iron Rod (Property Corner)	S29°E	15.51 feet
Metal Survey Sign Post	S03°W	14.8 feet
Centerline of U.S. Highway 41	East	67 feet

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape.
All distances to trees are measured to nails in side of tree.

Signed by William Lenca Date December 27, 1993
Surveyor's Michigan License No. 26461

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5			4	9	3		2		1		
3													
4	7	8			9		10		11		12		
5													
6	18	17			16		15		14		13		
7													
8	19	20			21		22		23		24		
9													
10	30	29			28		27		26		25		
11													
12	31	32			33		34		35		36		
13													

