

FEB 11 1998

Approved by Menominee County
Land Survey Remonumentation
Psr Group Under Act 345 Of
P.A. Of 1990 On 10/31 1997
Mc Davis RLS
Chairman

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MENOMINEE
(County)

Located in:

Corner Code #

1. Public Land Survey

T2N R 28W

K-6/7 (006)

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, William Lenca, in a field survey on Mar. 26, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by James H. Mullett - B.T.'s - B. Oak, 18" - N69°W - 05 lks.; Beech, 8" - N25.5°E - 37 lks. No evidence of the original corner or its accessories were recovered.
- 1970: Plat of "OAK PARK" by George B. Wilson, RLS No. 17607, shows this corner as part of the plat boundary and describes it in the plat legend as a 1/2 inch bar in 4" dia. conc. 36" long.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a broken 4 inch diameter concrete monument with a 1/2 inch diameter iron pin in the center in a location indicated by information on the plat of "OAK PARK". The measured distance from the W1/4 Corner to the Meander Corner is 2164.15 feet compared to the GLO distance of 2185 feet. There are remnants of a very old fence line running North from this location. We accepted the position of the concrete monument as the best available evidence of the position of the original corner, and replaced it with a new aluminum monument described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum cap stamped for corner location in place of broken Plat monument:

6" dia. White Ash	N16°E	53.44 feet	Scr. NBT
8" dia. White Ash	N76°E	11.01 feet	Scr. NBT
5/8" dia. Iron Rod	S60°E	70.82 feet	
5" dia. Maple	N60°W	76.12 feet	Scr. NBT
Metal Survey Sign Post	S15°W	2.0 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Apr. 10, 1997

97 NOV 21 PM 3:19
REGISTERED LAND SURVEYOR
STATE OF MICHIGAN
537, BKS

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

