Approved by Menominee County Land Survey Remonumentation Peer Group Under Act 345 Of

| | | | P.A. Of 1990 | PA OF 1990 On 12/20 199 95 | | | |
|--|---|---|--------------|---|--------------------------|-------------------|--|
| | DRNER RECORDATION Requirement of Act 74, I | | | 11kg/ | DUS | El | 2 |
| For corners in | equirement of Act 14, 1 | WIICH, F.A. 1970 | | _ 변경 변경 | | | |
| MENOMINEE Located In: | Corner Code # | | | | 5 DEC | GANICIA | |
| 1. Public Land Survey T _{33N} R 27N T R T 33N R 240 | | | | | 27 PH | D FOR ACCORD | |
| 2. Property Controlling S T R IN Section | | F | Register of | Deeds Sta | ∴ ;; ; 29 amp & | i. | ımber |
| 4. Lot No, Recorded Plat | | A | B C D | E F G | Н | IJ | K L |
| (SAME AS A-7 T33N-R26W) | | 2 3 | -65 | | 3 | | 1-1- |
| I, <u>William Lenca</u> , in a field survey on <u>N</u> requirements of P.A. 74, Michigan P.A. of 1970, the corner por conformance with regulations and rules therefore as required in the United States Department of the Interior, Bureau of Land Managethat the corner points mentioned in lines 3, 4 and 5 above were Board of Land Surveyors or by a Decree of a Court of Law recovered, found as expressed below: | ints mentioned in lines 1 and 2 the current manual of survey in- gement or by a decree of a Cour in conformance with the rules | 2 above were in structions of the tof Law and /or of the Michigan | -7 8 | 9 | 10 | 1423 | 13-24- |
| NOTE: Not more than 2 corners, all in the same town and | d range, may be recorded | 9 - | | | | | |
| on this certificate. | | 10 | -3029 | 28 | 2 ^{'7} | —2 6 — | 25- |
| | | 11 | _3132 | 33 | 34 | 35 | 36- |
| | | 12 | 31 32 | | | | |
| 1847: Original Survey - Twp Bdy - by James H. Mullett - B.T.'s - Fir, 8" - \$35°W - 6 lks; Fir, 10" - \$N15°W - 26 lks. All original evidence has been destroyed by county road improvements. 1848: Original Survey - Sec. Subd by John H. Mullett - B.T.'s - Beech, 8" - \$N41°E - 10 lks; Hemlock, 24" - \$23°E - 20 lks. All original evidence has been destroyed by county road improvements. 1901: Survey by Albert Hass, County Surveyor, shows this corner as it relates to other corners in Section 18, T33N-R26W. Corner is described as "4" Cedar Post set from Gov. B.T". No corner ties are given. 1984: L.C.R.C. No. 596 by George B. Wilson, RLS No. 17607, states that a Deep-1 Magnet was set from old fence lines and from A. Hass Survey. TIES: Deep-1 - NE - 39.0 feet; Deep-1 - SE - 48.6 feet - both destroyed by road improvements. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: In our 1995 remonumentation survey of T33N-R27W, we recovered a 1 inch square x 4" plastic case with a magnet encased (known as a Deep - 1). The position of the magnet matches with George Wilson's record measurements to corners North and South of this location as shown in Certified Survey No. 371. The measurement from this corner to the NE Corner of Section 13 is 5,279 feet as compared to Albert Hass' distance of 5282.64 feet. The corner falls 1.5 feet West of the present centerline of County Road No. 571. The corner position has been used by local surveyors for at least 11 years, and is accepted as the best available evidence of the position of the original corner. | | | | | | | |
| C. Description of monument for corner and accessories Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stam 6" dia. W. Pine 9" dia. Tamarack 7" dia. White Ash 8" dia Elm Metal Survey Sign Post NOTE: All bearings are magnetic bearings. All dis | N55°E 61.88 feet S52°E 56.08 feet S54°W 54.28 feet N41°W 69.71 feet N88°W 32.3 feet | Monument Box; Scr. NBT Scr. NBT Scr. NBT Scr. NBT | | * * Real State of the state of | SURV N 26 PED L | EYOR 6. 661 | The state of the s |
| tree. | | | | | | 54 | |
| Signed by (1) (Many Fritze | | Date | 1995 | | | ···· | |
| Surveyor's Michigan License No. 26461 | | | | | | | |