

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MENOMINEE
(County)

Located in:

Corner Code #

1. Public Land Survey

T33N R 27W E07

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, William Lenca, in a field survey on Jun 27, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by John Mullett - B.T.'s - Tamarack, 10" - N66°W - 20 lks; B. Ash, 12" - N50°E - 09 lks. All original evidence for this corner has been destroyed by county road improvements.
- 1983: Certified Survey No. 341, recorded by George B. Wilson, RLS No. 17607, shows this corner as it relates to other corners in Section 16, T33N-R27W (Sec. Subd.). The corner monument is not described and no B.T.'s are given.
- 1990: Certified Survey No. 705 recorded by William Lenca, RLS No. 26461, shows this corner as it relates to other corners in Section 17, T33N-R27W (Sec. Subd.) No corner monument is described and no B.T.'s are given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 3/4 inch diameter iron pipe in the centerline of an East - West County Road. This corner location was subsequently used in many surveys since 1981, including Certified Survey No.'s 341 and 705 mentioned above, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum cap stamped for corner location:

6" dia. White Ash	N50°E	72.10 feet	Scr. NBT
8" dia. Elm	S55°E	51.38 feet	Scr. NBT
13" dia. White Ash	S30°W	45.70 feet	Scr. NBT
9" dia. White Ash	N35°W	66.31 feet	Scr. NBT
Metal Survey Sign Post	South	80.0 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Nov. 20, 1996

