

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MENOMINEE

(County)

Located in:

Corner Code #

1. Public Land Survey

T33N R 27W

I-7

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, William Lenca, in a field survey on Mar. 08, 1995, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

RECEIVED FOR RECORD
95 DEC 27 PM 3:28
PAGE 263 BK 4
BARS/FA J. JOHNSON
REGISTERED SURVEYOR
No. 26461
Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2		6		5		4		3		2		1
3												
4		7		8		9		10		11		12
5												
6		18		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by John H. Mullett - B.T.'s - Beech, 4" - N06°E - 8 lks; Hemlock, 10" - S71°E - 17 lks. All original evidence has been destroyed by logging activities.
- 1896: Plat of Survey by Orson Burlingame, Surveyor, shows at distance of 2694 feet from this corner West to the NW Corner of Section 23, T33N-R27W.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

In our 1995 remonumentation survey in T33N-R27W, we found a 4" diameter Iron Pipe extending 5 feet above ground in line with ancient fences running East and South. We found that the distance from this corner West to the NW Corner of Section 23 measured 2688.34 feet as compared to Burlingame's measurement of 2694 feet. This corner has been used by local surveyors for several years, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
4" dia. Iron Pipe/3-1/4" dia. Alum. cap cemented in top stamped for corner location:

10" dia. White Ash	S50°W	3.50 feet	Scr. NBT
10" dia. White Ash	N50°W	46.57 feet	Scr. NBT
20" dia. White Ash	N19°W	56.12 feet	Scr. NBT
7" dia. White Ash	N04°E	43.63 feet	Scr. NBT
Metal Survey Sign Post	East	2.3 feet	



NOTE: All bearings are magnetic bearings. All distances are measured with a steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Dec. 06, 1995