

P.A. Of 1990 On 12/20 199 95  
Mr. David RLS.  
Chairman

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>MENOMINEE</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>33N</u> R <u>27W</u>	<u>M-7</u>
	T <u>  </u> R <u>  </u>	<u>  </u>
	T <u>  </u> R <u>  </u>	<u>  </u>
	T <u>  </u> R <u>  </u>	<u>  </u>
2. Property Controlling in Section	S <u>  </u> T <u>  </u> R <u>  </u>	<u>  </u>
	S <u>  </u> T <u>  </u> R <u>  </u>	<u>  </u>
3. Miscellaneous Property in Sec.	S <u>  </u> T <u>  </u> R <u>  </u>	<u>  </u>
	S <u>  </u> T <u>  </u> R <u>  </u>	<u>  </u>

RECEIVED FOR RECORD  
95 DEC 27 PM 3:29  
PAGE # 25 BK 4  
BARBARA A. JOHNSON  
REGISTERED PROFESSIONAL  
SURVEYOR  
No. 26461

Register of Deeds Stamp & File Number

4. Lot No.       , Recorded Plat         
5. Private Claims       

(SAME AS A-7 T33N-R26W)

I, William Lenca, in a field survey on Mar 09, 19 95 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2		6		5		4		3		2		1
3												
4		7		8		9		10		11		12
5												
6		18		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												

A. Description of original monument and accessories and/or subsequent restoration:

- 1847: Original Survey - Twp Bdy - by James H. Mullett - B.T.'s - Fir, 8" - S35°W - 6 lks; Fir, 10" - N15°W - 26 lks. All original evidence has been destroyed by county road improvements.
- 1848: Original Survey - Sec. Subd. - by John H. Mullett - B.T.'s - Beech, 8" - N41°E - 10 lks; Hemlock, 24" - S23°E - 20 lks. All original evidence has been destroyed by county road improvements.
- 1901: Survey by Albert Hass, County Surveyor, shows this corner as it relates to other corners in Section 18, T33N-R26W. Corner is described as "4" Cedar Post set from Gov. B.T". No corner ties are given.
- 1984: L.C.R.C. No. 596 by George B. Wilson, RLS No. 17607, states that a Deep-1 Magnet was set from old fence lines and from A. Hass Survey. TIES: Deep-1 - NE - 39.0 feet; Deep-1 - SE - 48.6 feet - both destroyed by road improvements.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

In our 1995 remonumentation survey of T33N-R27W, we recovered a 1 inch square x 4" plastic case with a magnet encased (known as a Deep - 1). The position of the magnet matches with George Wilson's record measurements to corners North and South of this location as shown in Certified Survey No. 371. The measurement from this corner to the NE Corner of Section 13 is 5,279 feet as compared to Albert Hass' distance of 5282.64 feet. The corner falls 1.5 feet West of the present centerline of County Road No. 571. The corner position has been used by local surveyors for at least 11 years, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box:

6" dia. W. Pine	N55°E	61.88 feet	Scr. NBT
9" dia. Tamarack	S52°E	56.08 feet	Scr. NBT
7" dia. White Ash	S54°W	54.28 feet	Scr. NBT
8" dia Elm	N41°W	69.71 feet	Scr. NBT
Metal Survey Sign Post	N88°W	32.3 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with a steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca  
Surveyor's Michigan License No. 26461

Date Dec. 11, 1995

