

SURVEY & REMONUMENTATION

APR 11 1995

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MENOMINEE
(County)

Located In:

Corner Code ##

1. Public Land Survey T 33N R 27W G-4R
2. Property Controlling S T R
3. Miscellaneous S T R
- Property in Sec. S T R

Other #1

4. Lot No. , Recorded Plat
5. Private Claims

William Lenca

June 09

94

I, William Lenca, in a field survey on June 09, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by John Mullett - B.T.'s - Beech, 4", N22°W, 22 lks & Beech, 18", S85°W, 18 lks. All original evidence for this corner has been destroyed by farming activities.
- 1977: L.C.R.C. No. 166 recorded by George B. Wilson, RLS No. 17607, shows this corner in a detail on the back of the corner certificate as being set mid point and on line between corners G-3 and G-5. There is no description of the corner monument, and no B.T.'s are given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A 3/4" dia. Aluminum rod 5 feet long with a 3-1/4" dia. Aluminum cap was found on line between corners G-3 and G-5, 470.63 feet North of the true corner location. The actual corner, based on a midpoint-on-line location, falls in the middle of a large tilled farm field. The owner of the property requested that no monument be placed in his field. The existing monument was accepted as a REFERENCE MONUMENT to corner G-4. The actual corner location (being M.P.O.L.) is accepted as a careful and faithful re-establishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Marked the existing 3/4" dia. Alum. Rod 5' long/ 3-1/4" dia. Alum. cap as REF MON:

6" dia. Poplar	N75°E	75.72 feet	Scr. NBT
9" dia. White Birch	N20°W	49.19 feet	Scr. NBT
9" dia. White Birch	S88°W	62.64 feet	Scr. NBT
9" dia. White Birch	S55°W	100.83 feet	Scr. NBT
Survey Sign Post	North	1.0 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca

Date July 09, 1994

Surveyor's Michigan License No. 26461

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of

P.A. 74 1970 On 12/19 19994

MEL DRAH RLS

ACTING

PAGE # 95 BK # 4

BARBARA MORRISON

REGISTER OF DEEDS

MENOMINEE MI 49856

4 DEC 12 AM 8:56

RECEIVED FOR RECORD

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

