

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 NR. 25 W.

Menominee COUNTY

DESCRIPTION OF CORNER Meander corner between Sec.'s 4-9

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 10" Cedar N 40° W 38 1/2 links

Marked "M.C. NBT"

5" Cedar S 29° W 36 1/2 links

Marked "M.C. NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Replaced meander corner from one hemlock B.T. bearing S 37° W 91 links.
Tree down and badly shattered.

Found by chaining with compass and along fence line from west.

SURVEYORS SEAL

SIGNED

REGISTERED LAND SURVEYOR

Billy D. Buckles

DATE 5/10/57