

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Menominee
(County)

Located In:

Corner Code ##

1. Public Land Survey T 34N R 26W L-6. ✓
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S 13 T 34N R 26W 5. ✓
in Section S 13 T 34N R 26W 10. ✓
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, David B. Babbitt, in a field survey on 6/16, 19 86, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L-6. Center of Section 13. Not previously established.

5. N1/16 corner on the N-S 1/4 line of Section 13. Not previously established.

10. S1/16 corner on the west section line of Section 13. Not previously established.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-6. Set at the intersection of the N-S and E-W 1/4 lines of Section 13.

5. Set M.P.O.L. between the center of Section 13 and the North 1/4 corner of Section 13.

10. Set M.P.O.L. between the West 1/4 corner and the SW section corner of Section 13.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | | |
|---------------------------|-------------------------|--------------------------|
| L-6. D.N.R. Monument | 5. D.N.R. Monument | 10. D.N.R. Monument |
| 8" h. maple N51W, 13.1' | 12" y. birch N12E, 4.5' | 9" cedar N63W, 6.55' |
| 7" " N17E, 11.8' | 5" hemlock N75W, 2.45' | 14" cedar N34E, 12.1' |
| 7" " S22E, 9.5' | 7" hemlock S52E, 6.7' | 8" cedar S19E, 14.9' |
| 12" r. maple S30W, 17.85' | 4" hemlock S24W, 6.95' | 5" w. birch S43W, 21.35' |

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by David B. Babbitt Date 7-16-86

Surveyor's Michigan License No. RLS 21558