

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Menominee  
(County)

Located In:

Corner Code 77

1. Public Land Survey T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_
2. Property Controlling S 13 T 34N R 26W 14, 3.  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

I, David Babbitt, in a field survey on 6/17/86, 19\_\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

14. S 1/16 corner on the east section line of Section 13. Not prev. est.
3. N 1/16 corner on the west section line of Section 13.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

14. Set MPOL between the East 1/4 corner and the SE section corner of Section 13.
3. Set MPOL between the West 1/4 corner and the NW section corner of Section 13.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

14. 1" pipe 4" alum cap. 3. 1" pipe 4" alum cap.  
5" cedar S22E, 6.9' 6" h.maple, N01W, 21.35'  
7" cedar S50W, 10.6' 5" h.maple, S23E, 16.95'  
9" cedar N82W, 9.6' 5" h.maple, S71W, 18.1'  
4" cedar N56E, 3.0' 4" w.birch, N55W, 11.8'

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by David B. Babbitt Date 9-11-86

Surveyor's Michigan License No. 21558