LAND CORNER RECORDATION CERTIFICATE F'ling Requirement of Act 74, Mich. P.A. 1970

For corne	ers in				
Men	ominee	Located In:	Corner Code ##		
1. Publi	ic Land Survey	т <u>34N я 26W</u>	<u>J-13, K-12.</u>		
		T R T R			
2 Pron	erty Controlling	T R S T R			
-	ection	S T R			
	ellaneous	S T R		legister of Deeds Stamp & File Number	
	erty in Sec.	S T R			
,	,				
				- A B C D E F G H I J K L M	
5. Priva	ite Claims			_ 2 6 5 4 4 3 2 4	
				3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
				4 - 7 - 8 - 10 - 11 - 12	
I. David Babbitt , in a field survey on11/7, 19 _89 5					
do berefy certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned					
in lines 1 and 2 above were in conformance with egulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land					
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 at 19 20 21 22 23 24					
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, mon imented, re-monumented, recovered, found as					
Court of expresses		e-established, mon imented, re-	monumented, recovered, found as	10 30 29 28 27 26 25	
•		orners, all in the same town a	nd range, may be recorded	11	
	on this certificate.	officia, an in the same town a	id lange, may be recorded	12 31 32 33 34 35 36	
	on the continues.			13	
A. Description of original monument and accessories and/or subsequent restoration:					
J-13.	J-13. South one quarter corner of Section 35. Wood post. J.H. Mullet, D.S 1848.				
Cedar 10, N75W, 17 Lks. Cedar 15, S50E, 17 Lks.					
	•				
K-12.	East one qua Cedar 10, S4	rter comer of Section 3W, 17 Lks. B. Ash 1	n 35. Wood post. J.H. 0, N65W, 20 Lks.	Mullet, D.S 1848.	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-13. Set from two cedar stumps with bearings and distances exact to fit record of OBT's. Could not find blazes or scribing but the SE one is quite rotten and has been run over with some kind of equipment and the NW one was cut low. Calls for stream 25 lks. and 100 lks. East are good and calls for six other stream calls Fast and West of this point fit reasonably well.					
				or good to the least a coming	
K-12. Set MPOL between the NE and SE section corners of Section 35. Could not locate OBT's.					
C. Des	cription of monume	ent for corner and aucessories	established to perpetuate locating	the position of the corner:	
J-13. DNR Monument. K-12. DNR Monument. 6" yellow birch, N21E, 32.9' 7" yellow birch, N42E, 40.65'					
8" cedar, S35E, 50.95' 4" cedar, S40E, 36.7'					
	dar, S19W, 64.		cedar, S14W, 44.65'		
	dar, N36W, 64.		medar, S76W, 20.25'		
				·	
		\			
	())	/ / //		_	
01	4//	IR. B. B. Ret	Date/	2-28-89	
Signed I		VV VV AT TO	Date		
Surveyo	r's Michigan Licens	se No21558	FORM A	PPROVEG BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28. 1971 Revised Way 14, 1975	

REVISED JAN., 1983