

APR 06 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MENOMINEE

(County)

Located In:

Corner Code #

- | | | |
|------------------------------------|-------------------------------------|------|
| 1. Public Land Survey | T <u>35</u> N R <u>26</u> W | C-13 |
| | T <u> </u> R <u> </u> | |
| | T <u> </u> R <u> </u> | |
| | T <u> </u> R <u> </u> | |
| 2. Property Controlling in Section | S <u> </u> T <u> </u> R <u> </u> | |
| | S <u> </u> T <u> </u> R <u> </u> | |
| 3. Miscellaneous Property in Sec. | S <u> </u> T <u> </u> R <u> </u> | |
| | S <u> </u> T <u> </u> R <u> </u> | |

4. Lot No. , Recorded Plat

5. Private Claims

(SAME AS CORNER C-1, T34N - R26W)

I, William Lenca, in a field survey on June 30, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1847: Original Survey by Henry Floyd (Township Boundary) - B.T.'s - B. Ash, 10" - N32°E - 28 lks.; Cedar, 15" - N36°W - 33 lks. All original evidence for this corner has been destroyed by county road improvements.
- 1848: Original Survey by James H. Mullett (Sectional Subdivision) - B.T.'s - Cedar, 16" - S25°W - 25 lks.; Hemlock, 10" - S09°E - 37 lks. All original evidence for this corner has been destroyed by county road improvements.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We set this corner in the centerline of an East - West County Road and in line with an old fence North. This location fits existing lines of occupation and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box:

4" dia. Cedar	N32°E	68.24 feet	Scr. NBT
12" dia. Cedar	S06°E	50.86 feet	Scr. NBT
4" dia. Tamarack	S52°W	106.06 feet	Scr. NBT
4" dia. Cedar	N21°W	87.60 feet	Scr. NBT
Metal Survey Sign Post	South	46.4 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca

Date Aug 24, 1998

Surveyor's Michigan License No. 26461

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
PA. Of 1990 On 12/14, 1998
M. L. Dineen PLS
Chairman

RECEIVED FOR RECORD
99 JAN 27 PM 1:33
PAGE # 748 BKS
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE, MI 49858

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

