

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in  
**T** Menominee  
 (County)

Located In:

Corner Code 77

1. Public Land Survey	T	34N	R	28W	B4
	T		R		
	T		R		
	T		R		
2. Property Controlling in Section	S	7	T	R	3
	S		T	R	4
3. Miscellaneous	S		T	R	8
Property in Sec.	S		T	R	

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_

I, Keith Sackett, in a field survey on August 7, 1991, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4				8		8		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

<b>B4</b> Center quarter corner of Section 7. Not set in original survey nor subsequently, apparently.	<b>3</b> North one-sixteenth corner common to Sections 7 and 12. Not set in original survey nor subsequently, apparently.	<b>4</b> Northwest one-sixteenth corner of Section 7. Not set in original survey nor subsequently, apparently.	<b>8</b> Center west one-sixteenth corner of Section 7. Not set in original survey nor subsequently, apparently.
---	--	---	---

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

<b>B4</b> Set at intersection of E-W quarter line and a line from the north quarter corner with a mean bearing of the east and west section lines.	<b>3</b> Set midway and on line.	<b>4</b> Set at the intersection of the north and west one-sixteenth lines.	<b>8</b> Set midway and on line.
---	-------------------------------------	--	-------------------------------------

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<b>B4</b> Set 1" I.D. x 32" iron pipe with 4" aluminum cap. 6" aspen N58E 19.5', BT 6" aspen S72E 24.7', BT 5" aspen S25W 25.4', BT 12" oak N56W 65.3', BT	<b>3</b> Set 1" I.D. x 32" iron pipe with 4" aluminum cap. 10" balsam poplar S86E 16.6', BT 5" American elm S66E 18.5', BT 7" tamarack N22E 87.2', BT 6" tamarack N57W 69.4', BT	<b>4</b> Set 1" I.D. x 32" iron pipe with 4" aluminum cap. 5" black ash N33E 10.15', BT 6" tamarack S63E 25.35', BT 5" black ash N84W 10.85', BT 6" black ash N36W 12.05', BT	<b>8</b> Set 1" I.D. x 32" iron pipe with 4" aluminum cap. 6" red maple N46E 33.6', BT 10" white pine S03E 36.6', BT 8" red maple S44W 25.7', BT 16" white pine N43W 20.7', BT
---	---	--	---

Signed by Keith Sackett Date \_\_\_\_\_

Surveyor's Michigan License No. 19006

