

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	Located In:	Corner Code #
1. Public Land Survey	T 34N R 29W	MC S of G04[005]
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Jeremy J. Pipp, in a field survey on 4/03/2012AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(MC S of G04)[005] Meander Corner common to Sections 9 and 10 on left bank of Menominee
River. 1852: Francis Coleman, DS. Set meander post witnessed by: Forked Maple 24 N44W
94 links (62.04'); Maple 20 N30E 67 links (44.22').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MC S of G04)[005] No evidence of original survey or subsequent restoration found. Corner
position reestablished by extending a line South from the West One-Quarter corner of
Section 10 along a line that is parallel with the East line of Section 10. GLO distance
from the One-Quarter corner to this position is 21.02 Chains (1387.32 feet); this position
falls on an unstable bank. Monumented witness position 1368.59 feet South of One-Quarter
Corner and +/-30 Feet from the Waters Edge. Position is accepted as a careful and faithful
WITNESS TO the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(MC S of G04)[005] DNR monument
17" Ash N01E 43.54' (MC,NBT)
22" Maple S41E 15.35' (MC,NBT)
19" Maple S20W 27.52' (MC,NBT)
23" Maple N69W 3.52' (MC,NBT)

All trees are blazed, scribed, painted,
and signed. Measurements are to nail in
side of tree, bearings are magnetic. A
metal rail & sign were set North 1.5
feet.

Signed by Jeremy J. Pipp
Surveyor's Michigan License No. 50447



July 17, 2012

For the Michigan Department of Natural Resources, Forest Resources Division