

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee Located in: Corner Code #
1. Public Land Survey T 34N R 29W MC E of J05[009]
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Jeremy J. Pipp, in a field survey on 4/05/2012AD do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(MC E of J05)[009] Meander Corner common to Sections 11 and 14 on left bank of Menominee River. 1852: Francis Coleman, DS. Set meander post witnessed by: Sugar 6 N53E 14 links (9.24'); Ironwood 9 S23E 20 links (13.20').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MC E of J05)[009] No evidence of original survey or subsequent restoration found. Corner position reestablished by extending a line from the Southeast corner of Section 11 West along a line that is parallel to the GLO plat relationship (North line of S11 = S 89deg-47min E, South line S11 = West) and GLO notes. GLO distance from the Section corner to this position is 30.96 Chains (2043.36 feet); this position falls near un-stable bank. Monumented witness position 2033.36 feet West of Section Corner and 15 Feet from the Waters Edge. Position is accepted as a careful and faithful WITNESS TO the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(MC E of J05)[009] DNR monument
10" Oak N68E 8.80' (MC,NBT)
10" Maple S10E 19.55' (MC,NBT)
16" Maple N67W 4.55' (MC,NBT)
9" Ironwood N08W 10.70' (MC,NBT)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A metal rail & sign were set East 1.5 feet.



Signed by [Signature] July 17, 2012
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Resources Division