

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 11 T 34N R 29W S 11 T 34N R 29W S _____ T _____ R _____	5 6 _____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Jeremy J. Pipp, in a field survey on 4/04/2012AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(05) Center-North One-Sixteenth corner of Section 11. Not set in original survey, no
evidence of subsequent establishment.

(06) Northeast One-Sixteenth corner of Section 11. Not set in original survey, no
evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(05) Corner position established mid-point and on-line between the Center One-Quarter
corner and the North One-Quarter corner of Section 11. Monument located at base of red
Maple.

(06) Corner position established at the intersection of the North and East One-Sixteenth
lines of Section 11.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(05) DNR monument
12" Red Maple N76E 32.46' (1/16S,BT)
20" Red Maple S66E 9.96' (1/16S,BT)
13" White Pine S53W 18.64' (1/16S,BT)
8" Oak N80W 7.19' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

(06) DNR monument
7" Red Maple N62E 24.85' (1/16S,BT)
21" Oak S43E 12.71' (1/16S,BT)
9" Oak S53W 8.27' (1/16S,BT)
9" Red Maple N42W 22.58' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp Date July 17, 2012
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Office of Professional Facilities



20056

20057

Revised May 14, 1975
Revised Jan., 1983
Revised Oct., 1995