

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 12 T 34N R 29W	6
	S 12 T 34N R 29W	8
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Jeremy J. Pipp, in a field survey on 3/20/2012AD do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(06) Northeast One-Sixteenth corner of Section 12. Not set in original survey, no  
evidence of subsequent establishment.

(08) Center-West One-Sixteenth corner of Section 12. Not set in original survey, no  
evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(06) Corner position established at the intersection of the North and East One-Sixteenth  
lines of Section 12.

(08) Corner position established mid-point and on-line between the Center One-Quarter  
corner and the West One-Quarter corner of Section 12.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(06) DNR monument  
6" Tamarack N07E 88.70' (1/16S,BT)  
6" Tamarack N40E 50.30' (1/16S,BT)  
7" Tamarack S46E 102.85' (1/16S,BT)  
4" Tamarack N44W 73.90' (1/16S,BT)

All trees are blazed, scribed, and  
painted. Measurements are to nail in  
side of tree, bearings are magnetic.

(08) DNR monument  
11" Oak N20E 27.37' (1/16S,BT)  
8" Oak S71E 4.38' (1/16S,BT)  
22" Red Pine S61W 35.60' (1/16S,BT)  
6" Oak N48W 29.09' (1/16S,BT)

All trees are blazed, scribed, and  
painted. Measurements are to nail in  
side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp  
Surveyor's Michigan License No. 50447

July 16, 2012

For the Michigan Department of Natural Resources, Office of Land and Water Facilities



20039

20040

MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995