

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	Located In:	Corner Code #
1. Public Land Survey	T 34N R 29W	104
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Jeremy J. Pipp, in a field survey on 4/03/2012AD do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I04) Quarter Corner common to Sections 10 and 11. 1852: Francis Coleman, DS. Set post  
witnessed by: Elm 14 N82E 83 links (54.78'); Elm 30 S27W 43 links (28.38').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I04) No evidence of original survey or subsequent restoration found. Corner position  
reestablished by single proportionate measurement between 'Enter open marsh' call North  
(at 14.25 ch) & 'Leave dry channel' call South (at 44.15 ch)[both Calls noted to the  
Hundredth of a chain]. Distance to Section Corner North and 'Enter ancient channel' call  
North check well. Location falls in seasonal flooding channel. Position is accepted as a  
careful and faithful REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I04) DNR monument  
22" Maple S14E 35.08' (1/4S,NBT)  
15" Ash S66W 72.54' (1/4S,NBT)  
17" Ash N70W 43.30' (1/4S,NBT)  
22" Red Maple N20W 32.85' (1/4S,NBT)

All trees are blazed, scribed, painted,  
and signed. Measurements are to nail in  
side of tree, bearings are magnetic. A  
metal rail & sign were set North 1.5  
feet.

Signed by Jeremy J. Pipp

Surveyor's Michigan License No. 50447



Date July 17, 2012

For the Michigan Department of Natural Resources, Office of Land and Facilities