

SURVEY &
REMONUMENTATION

JUN 23 1994

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of

P.A. Of 1990 On 5/10 1994

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION
For corners in
MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 34N R 27W

E-11

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, William Lenca, in a field survey on March 23, 19 94,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

ORIGINAL B.T.'s: Cedar, 6", N87°E, 12 lks
Spruce, 10", S33°W, 07 lks

Original Survey by James H. Mullett in 1848. All original evidence for this corner has been destroyed by Farming and
wood harvesting activities.

PERPETUATION: This corner is shown in Certified Survey No. 362 as recorded by George B. Wilson, RLS No. 17607, in
Aug. of 1983. Although the corner monument is not described in Mr. Wilson's survey, his normal practice was to set
a standard county monument, as described in part "B".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a 3/4" diameter Aluminum Rod 5 feet long with a 3-1/4" Alum. cap at an ancient fence corner. This monument was
set by George B. Wilson, RLS 17607, and fits with the recorded distances (as shown in Certified Survey No. 362), and is
accepted as the best available evidence for the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Accepted 3/4" dia. Alum. Rod 5' long/3-1/4" dia. Alum. cap stamped for Corner location:

10" dia. Maple	Scr. NBT	N10°E	9.80 feet
6" dia. Oak	" "	N65°E	38.32 feet
5" dia. White Ash	" "	S07°E	52.55 feet
8" dia. Maple	" "	N74°W	45.29 feet
Survey Sign Post		S65°W	1.0 feet

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca Date April 22, 1994

Surveyor's Michigan License No. 26461

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19
REVISED MAY 14, 19
REVISED JAN., 19

RECEIVED FOR RECORD
94 MAY 20 PM 3:31
PAGE # 65 BK 4
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE, MI 49858

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

