

SURVEY & REMONUMENTATION

FEB 11 1998

Approved _____ County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. of 1990 On 12/18 199 7
McLain RLS
Chairman

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION 31

For Corners in
MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T34N R 27W A/B-13

T R (010)

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

SAME AS CORNER A/B-1, T33N-R27W

I, William Lenca, in a field survey on Nov. 26, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	10		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1848: Original Survey by James H. Mullett - B.T.'s - W. Ash, 10" - N59°E - 08 lks.; B. Ash, 15" - S17°E - 12 lks. All original evidence for this corner has been destroyed by river erosion and ice shoves.

1971: Plat of Survey by George B. Wilson, RLS No. 17607, shows an iron set 30' from the Menominee River and 693.57 feet West of the South 1/4 Corner of Section 31, T34N-R27W.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 5/8 inch diameter iron rod on the bank of the Menominee River in a position as indicated on George B. Wilson's 1971 survey. The corner falls on a straight line projection of the line between the SE Corner and the South 1/4 Corner of Section 31 and at a distance of 693.20 feet West of the S1/4 (Wilson's recorded distance = 693.57 feet). This corner has been used by local surveyors for many years, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum cap stamped for corner location over existing iron:

16" dia. Oak	S29°W	37.93 feet	
5" dia. White Ash	S58°W	24.43 feet	Scr. NBT
16" dia. Basswood	N06°W	10.28 feet	Scr. NBT
Menominee River	West	30 feet	
Metal Survey Sign Post	West	1.1 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Dec. 12, 1997

