

# SURVEY & REMONUMENTATION

FEB 11 1998

Approved by Menominee County  
Land Survey Remonumentation  
Peer Group Under Act 345 Of  
P.A. Of 1996 On 12/30 1997  
Mr. Davis RLS  
Chairman

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

### SECTION

For corners in

MENOMINEE

(County)

Located in:

Corner Code #

1. Public Land Survey

T 35N R 25W K-06

T R

T R

T R

T R

2. Property Controlling  
In Section

S T

T R

3. Miscellaneous  
Property in Sec.

S T

T R

S T

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, William Lenca

, in a field survey on Sept 22, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

#### A. Description of original monument and accessories and/or subsequent restoration:

1848: Original Survey by James H. Mullett - B.T.'s - B. Ash, 8" - N20°W - 14 lks; B. Ash, 8" - S74°E - 17 lks. All original evidence for this corner has been destroyed by logging activities.

1970: Survey by George B. Wilson, RLS No. 17607, states this corner was re-set by using single proportionate measurement. The corner is shown in relation to other corners in Section 13. No corner monument is described and no B.T.'s are given.

#### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We Recovered a 4 inch diameter concrete monument and old squared post in location matching record measurements as shown in George Wilson's survey dated 1970. This corner has been accepted and used by local surveyors for at least 27 years, and is accepted as the best available evidence of the position of the original corner.

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3-1/4" dia. Alum. cap stamped for corner location on existing 4" dia. Concrete Monument:

14" dia. White Ash

N75°E

33.63 feet

Scr. NBT

7" dia. Cedar

S32°W

17.33 feet

Scr. NBT

14" dia. Hemlock

N72°W

48.67 feet

Scr. NBT

6" dia. Cedar

N11°W

22.59 feet

Scr. NBT

Survey Sign Post

North

1.0 feet

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by

Surveyor's Michigan License No.

26461

Date

Sept 30, 1997

