

SURVEY & REMONUMENTATION

JAN 09 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County  
Land Survey Remonumentation  
Peer Group Under Act 345 of  
P.A. Of 1990 On 7/13, 2000  
W. Davis RLS  
Chairman

For corners in  
MENOMINEE  
(County)

Located In: Corner Code #

- |                                    |                                     |     |
|------------------------------------|-------------------------------------|-----|
| 1. Public Land Survey              | T <u>35</u> N R <u>26</u> W         | E-7 |
|                                    | T <u>  </u> R <u>  </u>             |     |
|                                    | T <u>  </u> R <u>  </u>             |     |
|                                    | T <u>  </u> R <u>  </u>             |     |
| 2. Property Controlling in Section | S <u>  </u> T <u>  </u> R <u>  </u> |     |
|                                    | S <u>  </u> T <u>  </u> R <u>  </u> |     |
| 3. Miscellaneous Property in Sec.  | S <u>  </u> T <u>  </u> R <u>  </u> |     |
|                                    | S <u>  </u> T <u>  </u> R <u>  </u> |     |

Book 6 Page 153

RECEIVED FOR RECORD  
13 DEC 2000 10:16:09 A  
BARBARA MORRISON  
REGISTER OF DEEDS  
MENOMINEE, MI 49858

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, William Lenca, in a field survey on Sep., 19 00 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5			4			3		2	1
3													
4	7			8			9			10		11	12
5													
6	18			17			16			15		14	13
7													
8	19			20			21			22		23	24
9													
10	30			29			28			27		26	25
11													
12	31			32			33			34		35	36
13													

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by James H. Mullett - B.T.'s - Beech, 6" - S78°W - 20 lks.; Beech, 8" - S68°E - 21 lks. All original evidence for this corner has been destroyed by County Road improvements.
- 1976: L.C.R.C. No. 130, Book 1, by George B. Wilson, RLS No. 17607 states "Dug hole with county equipment 10' x 10' x 5' deep and found section of old wood stake, pointed at end. Set concrete Monument 4" dia. x 36" long with 1/2" dia. iron rod 4 inched below pavement. Nothing near for ties.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found a 4 inch square concrete monument (as described in L.C.R.C. No. 130, Book 1 in part A) with 3-1/4 inch diameter aluminum cap in centerline of a 4 way County Road intersection. The 1976 Corner Record states "found section of old wood stake, pointed at end", but does not indicate that this was an original post. We therefore accepted the concrete monument as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Monument Box over existing 4" square x 36" long concrete monument/3-1/4" dia. Alum. cap stamped for corner location

5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	N47°E	41.66 feet	1.0' West of Tel. Box
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	S35°E	47.95 feet	1.0' North of Fence Cor.
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	S39°W	46.03 feet	1.0' East of Power Pole
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	N27°W	47.72 feet	1.0' South of Power Pole
Metal Survey Sign Post	S35°E	48.55 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca  
Surveyor's Michigan License No. 26461

Date Oct. 13, 2000

