

## MAR 29 2000

## SECTION

## LAND CORNER RECORDATION CERTIFICATE

Approved by Menominee County Land Survey Remonumentation Peer Group Under Act 345 Cf						
·	pa of 1	99 <b>)</b> (a.	49//		109.2	
•		100	14411	RLS	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	BK.	6	Chairma Pg.	//5	_	
	RE	CE IVED	FOR REC	ORD		
	28 D	EC 1999	3:56:	09 PM	٠	
	R	FRISTE	NORRIS	:DS		
	<u>ME</u>	NOM INE	E. MI 49	1958		
Regis	ster of	Deeds	Stamp 8	& File N	lumher	
			<u>Otamp (</u>		idilibei	
A В	C D	E F	GН	I J	K L	
6 	5-		_		1-1-	
	8-	9-	10-	11-	12-	
			$+\bar{+}$			
—18— 	17-	16	15-	14-	13-	
19	20-	21-	22_	23	24-	
-			11			
—зю— 	- 2 <sup>i</sup> 9-	2'B- 	2'7	26-	25-	
_3 <sub>1</sub>	32-	33	34	35_	36-	
	<u> </u>					
n, 8"	- N84 <sup>0</sup>	E - 22	lks. Al	l origin	ıal	
			rmerly :			
by George B. Wilson, RLS 17607, in Post - N55 <sup>0</sup> E - 52.18'; Cor. Post of 34.36'.						
ent fe	nce lin rt Hass	e runn 's reco	ted in th ing Nort rd distar le evide	th. The		
of the	corner	*	WILEI LAN LAN SURVI 264	CA ND IYUR N.		
nces to trees are to nail in side of tree.						

For corners in	£ IIII	ng Requirement of Act 74, Mich	. P.A. 19/0
MENOMINEE	Located In:	Corner Code #	BK
(County)	•	·	<u></u>
1. Public Land Survey	T <u>35N</u> R TR TR		28
Property Controlling in Section     Miscellaneous	TR S TR S TR S TR		
Property in Sec.	S TR		Register o
4. Lot No, Reco 5. Private Claims	rded Plat	•	A B C I

conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

, in a field survey on \_\_\_Nov.

requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Description of	foriginal monument and	l accessories and	Var eubasauset	rootoration:

Sectional Subdivision by James H. Mullett - B.T.'s - Beech, 6" - N140W - 16 lks.; Lyn 1848: evidence for this corner has been destroyed by county road improvements.

, 19 99 do hereby state that under

4

6

8 9

10 11 12

- 1900: Subd. of Section 24, T35N-R27W by Albert Hass states "3" Cedar Post in center of roa Distances shown to other corners in Section 24.
- 1990: L.C.R.C. No. 890, Bk 3, by William Lenca, RLS No. 26461 - Found Rairoad Spike sel center of Co. Rds E-W-S and in line with ancient fence North. TIES: Cemetery Gate chain link fc - S43°E - 46.98'; W. Ash, 6" - S31°W - 58.67'; W. Ash, 12" - N28°W - 3

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered the railroad spike and ties as described in LCRC No. 890, book 3 (see part "A"). centerline intersection of county roads running East - West and South, and in line with an ancie measurement from this corner to the Section corner 1/2 mile South is 2717.71 feet compared to 2721.84'. The position of this corner fits well with existing lines of occupation, and is accepted position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position

Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box:

Lower hinge pin of cemetary gate	N 530 E	52.33 feet	
	S 44 <sup>0</sup> E		
Corner post of Chain Link Fence		46.98 feet	
8" W. Ash	S 250 W	58.67 feet	Scr. NBT
14" W. Ash	N 360 W	34.36 feet	Scr. NBT
Metal Survey Sign Post	North	30.80 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distan

Signed by 18 Many Frence.	Date	Nov. 23, 1999	· · · .
Surveyor's Michigan License No26461		·	