MAR 29 2000

SECTION


LAND CORNER RECORDATION CERTIFICAT Filing Requirement of Act 74, Mich. P.A. 1970

ſE	Approved by Menominee County Land Survey Remonumentation Peer Group Under Act 245 Cf PA Of 1990 On 1990 Schalman
	Bx 6 Pg. 86
	RECEIVED FOR RECORD 28 DEC 1999 3:56:09 PM
	BARBARA MORRISON REGISTER OF DEEDS MENOMINEE. MI 49858
	2 Cilo Number
	Register of Deeds Stamp & File Number
1	ABCDEFGHIJKL

For corners in				
MENOMINEE	Located In:	Corner Code #		
(County)				
1. Public Land Survey	Τ	R_27W R R R	M-3	
Property Controlling in Section Miscellaneous Property in Sec.	S T S T S T	R R R		
4. Lot No, Reco 5. Private Claims SAME AS CORNER A	A-3, T35N-R26W		•	
requirements of P.A. 74, Mich conformance with regulations a United States Department of the	nd rules therefore as re	equired in the	mentioned in lines 1 and 2 about a decirrent manual of survey instruction or by a decree of a Court of conformance with the rules of the stabilished.	Law and /or

that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Twp. Boundary by H. Floyd - B.T.'s - Beech, 6" - S46°W - 27 lks; Beech, 6" - N20°W - 9 lks 1847:

Sectional Subdivision by James H. Mullett - B.T.'s - Beech, 6" - S87°E - 11 lks.; Beech, 6" - N25°E - 27 lks. All original 1848:

evidence for this corner has been destroyed by years of decay.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

In a retracement of the East Line of Section 1, T35N-R27W, we found an ancient fence corner (fences run N-S-E-W) at a location of 2664.99 feet South of the E1/4 Corner of Section 1 and 2637.78 feet North of the E1/4 Corner of Section 12, T35N-R27W. We accepted this location as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

Set 2"dia. Aluminum Pipe 30" long/3-1/4" dia. Alum cap stamped for corner location:

15" dia. Hemlock 5" dia. Ironwood 9" dia. H. Maple	N 540 W		Scr. NBT Scr. NBT Scr. NBT
9" dia. H. Mapie 7" dia. Ironwood Metal Survey Sign Post		.50 feet	Scr. NBT

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Falke
Surveyor's Michigan License No. 26461

DateNov. 23, 1999

LENCA SESSIVEY OF