SURVEY &
REMONINATION

APR 96 1999

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Land Survey Remonumentation Peer Group Upder Act 345 Of	1
	<u> </u>
Service & Wain	<u>, 7, 5</u>

Approved by Menominee County

MENOMINEE	Located In:	In: Corner Code#	
(County)		and the second	
1. Public Land Survey	T <u>35N</u> F TF TF		
Property Controlling in Section Miscellaneous Property in Sec.	S TF S TF S TF		


Register of Deeds Stamp & File Number

4. Lot No,	Recorded Plat					
5. Private Claims _	· · · · · · · · · · · · · · · · · · ·					

(SAME AS CORNER A-09, T35N-R26W.)

1998 _do hereby state that under Nov. in a field survey on William Lenca requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



- Description of original monument and accessories and/or subsequent restoration:
 - Original Survey Township Boundary by H. Floyd B.T.'s B. Ash, 10" S47°W 44 lks.; Elm, 22" N76°W 75 lks. 1847:
 - Original Survey Sectional Subdivision by James H. Mullett B.T.'s B. Ash, 12" S23°E 23 lks.; Cedar, 8" N63°E -1848; 08 lks. All original evidence for these corners have been destroyed by county road improvements.
 - Albert Hass, Co. Surveyor, shows this corner in relation to other Cor.s in Sec. 24 states set 4" Ced. Post in center of Rd.
 - L.C.R.C. Number 261 by Gerald W. Carlson states, "FD. REMAINS OF SQ. CEDAR POST BELOW BLKTOP RD.; SET 1900: 1980: 5/8" x 24" IRON w/RLS CAP IN MONUMENT BOX, 2' NORTH OF CENTERLINE CO. RD. "G-12", ON CENTERLINE GRAVEL RD. N. & S." TIES: Power Pole - N30°W - 59.37'; Ash, 4" - N31°E - 63.54'; Ash, 16" - S49°E - 55.50';

Basswood, 3" - S26°W - 67.10'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 5/8 inch diameter iron rod with plastic identification cap marked RLS 24589 inside of a square cast iron monument box 9 inches below the present asphalt road surface per L.C.R.C. No. 261. Based on Gerald Carlson's Land Corner Record, we accepted this position as a re-monumentation of Albert Hass' Cedar Post set in 1900. Since there is no record evidence that this post was established from Original Evidence, we accepted it as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3-1/4" dia. Alum. cap stamped for corner location over existing 5/8" Iron Rod in Monument Box:



NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

11012. 1— 11			
10) Min 5100		Dec. 12, 1997	
Signed by <u>(1) Main Bross</u>			
Survoyade Michigan License No.	76461		