

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Menominee

(County)

Located In:

Corner Code ##

1. Public Land Survey

T R  
T R  
T R  
T R

2. Property Controlling  
in Section

S 22 T 35N R 28W  
S T R

3. Miscellaneous  
Property in Sec.

S T R  
S T R

6, 1, 2.

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, David B. Babbitt, in a field survey on 8/1/88, 19 ,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

6. NE 1/16 corner of Section 22. No previous record.

1. W 1/16 corner on the north section line of Section 22. No previous record.

2. E 1/16 corner on the north section line of Section 22. No previous record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1. Set at the computed center of the NE 1/4 of Section 22 by closed traverse.

1. Set MPOL between the north 1/4 corner and the NW section corner of Section 22.

2. Set MPOL between the north 1/4 corner and the NE section corner of Section 22.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1. DNR Monument

7" b.ash, N21E, 23.0'

5" b.ash, S36W, 13.5'

10" cedar, S20E, 30.8'

5" b.ash, N77W, 18.3'

1. DNR Monument

7" r.maple, N36W, 24.0'

6" r.maple, S54W, 12.1'

10" spruce, N75E, 37.9'

8" r.maple, S19E, 15.2'

2. DNR Monument

6" cedar, S03E, 21.8'

5" spruce, S32E, 6.95'

9" cedar, N20E, 29.9'

9" cedar, N23W, 30.7'

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	16		17		18		19		20		21		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by David B. Babbitt Date 9-29-88

Surveyor's Michigan License No. 21558