

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S 32 T 35N R 28W S 32 T 35N R 28W S _____ T _____ R _____	2 6 _____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____ _____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Jeremy J. Pipp, in a field survey on 2/14/2012AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(02) East One-Sixteenth corner common to Sections 29 and 32. Not set in original survey,
no evidence of subsequent establishment.

(06) Northeast One-Sixteenth corner of Section 32. Not set in original survey, Found
Capped Rebar (PS#26461) with 3 foot high 1 1/4" Guard pipe and a Chest Blazed tree facing
position.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(02) Corner position established mid-point and on-line between the North One-Quarter
corner and the Northeast corner of Section 32.

(06) Corner position calculated at the intersection of the North and East One-Sixteenth
lines of Section 32. Found Capped Rebar checked well for position was accepted. Set MDNR
monument over the top of said existing monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(02) DNR monument
23" Red Pine N39E 69.03' (1/16S,BT)
7" Maple S48E 5.73' (1/16S,BT)
7" Oak S72W 22.85' (1/16S,BT)
5" Cherry N15W 17.58' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp
Surveyor's Michigan License No. 50447

(06) DNR monument
6" Sugar N23E 26.51' (1/16S,BT)
13" Basswood S19E 33.18' (1/16S,BT)
7" Sugar S53W 37.20' (1/16S,BT)
4" Sugar N48W 17.51' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Date: July 16, 2012

For the Michigan Department of Natural Resources, Office of Land and Facilities

20025

20026



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
Revised May 14, 1975
Revised Jan., 1983
Revised Oct., 1995