

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 31 T 35N R 28W	8
	S 31 T 35N R 28W	15
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Jeremy J. Pipp, in a field survey on 3/19/2012AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(08) Center-West One-Sixteenth corner of Section 31. Not set in original survey, no
evidence of subsequent establishment.

(15) West One-Sixteenth corner common to Sections 31 and 6. Not set in original survey;
Found 1/2" Pipe N07E 18.5 feet from calculated position, not of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(08) Corner position established by single proportionate measurement between the Center
One-Quarter corner and the West One-Quarter corner of Section 31.

(15) Corner position established by single proportionate measurement between the South One-
Quarter corner and the Southwest corner of Section 31.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(08)	DNR monument	(15)	DNR monument
11" Tamarack	N57E 6.11' (1/16S,BT)	15" Oak	N79E 31.08' (1/16S,BT)
6" Cedar	S53E 17.90' (1/16S,BT)	9" Red Maple	S59E 50.24' (1/16S,BT)
9" Cedar	S38W 7.24' (1/16S,BT)	6" Oak	S42W 19.04' (1/16S,BT)
6" Tamarack	N33W 19.06' (1/16S,BT)	13" Oak	N35W 37.51' (1/16S,BT)
All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.		All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.	

Signed by Jeremy J. Pipp Date July 16, 2012

Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Office of Land and Fisheries

20037

20033



MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995