

MAR 29 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 of

P.A. of 1989 On 12/28 1999
McL. Davis RLS
Chairman

For corners in

MENOMINEE
(County)

Located in:

Corner Code #

1. Public Land Survey

T 35N R 28W K-12/13 (002)

T R
T R
T R

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous
Property in Sec.

S T R
S T R

BK. 6 Pg. 77

RECEIVED FOR RECORD
28 DEC 1998 3:56:09 PM
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE, MI 49858

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, William Lenca, in a field survey on Dec., 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

- 1852: Original Survey by Francis Coleman - B.T.'s - Hemlock, 10" - N72°W - 29 lks.; Lynn, 10" - N68°E - 23 lks. All original evidence for this corner has been destroyed by river erosion and ice jams.
- 1987: Certified Survey Number 555, by William Lenca RLS 26461, indicates in the legend that a 1/2" diameter Iron Rod was found where the West line of Section 36, T35N-R28W intersects the Menominee River.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 5/8 inch diameter iron rod on the high bank of the Menominee River in a location as shown in Certified Survey No. 555. The corner monument is incorrectly described in the legend of the Certified Survey as a 1/2 inch diameter iron rod. The corner location fits with the extension South of an ancient fence to the North, fits reasonably well with the GLO distance from the W1/4 Corner of Section 36 South to the River, has been used by local surveyors for several years, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" dia. Aluminum Pipe 30" long 3-1/4" dia. Alum cap stamped for corner location:

16" dia. White Ash	N07°E	28.27 feet	Scr. NBT
11" dia. Black Ash	N45°E	53.15 feet	Scr. NBT
13" dia. Oak	S42°W	34.10 feet	Scr. NBT
9" dia. Basswood	N43°W	24.85 feet	Scr. NBT
Metal Survey Sign Post	South	0.6 feet	
Menominee River	South	28' +/-	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Dec. 17, 1998

