## LAND CORNER RECORDATION CERTIFICATE

## MENOMINEE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED	IN -:		CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	т	N. S., R	- W.	
2. PROPERTY CONTROLL- 14 ING IN SECTION———	,т	N. S., R. <u>29</u>	*. W.	5
3. MISCELLANEOUS PROPERTY IN SECTION	,т	N. S., R	E. W	
4. LOT NO, RECOR	DED PLAT	· 	<del></del>	

5. PRIVATE CLAIMS_	5.	PRI	٧AT	E CL	AIMS _
--------------------	----	-----	-----	------	--------

REGISTER OF DEEDS STAMP AND FILING NUMBER

David B. Babbitt ., do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 4 re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on\_\_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the roles of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and/or subsequent restoration:
- 5 North 1/16 Cor. on the N-S 1/4 line of Sec. 14; not previously established.

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- 5 Set M.P.O.L. between the Ctr. of Sec. and the N. 1/4 Cor. of Sec. 14.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 5 D.N.R. Monument; 5" J. Pine  $N51^{\circ}E$  29.2'; 12" Oak  $N6^{\circ}E$  19.8'; 4" J. Pine  $S84^{\circ}E$  17.4'; 7" Poplar  $S73^{\circ}W$  1.0'.

(BEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.